


FIGURE 1



A Batch Dissolver

FIGURE 2




FIGURE 3





FIGURE 4



A Schematic for Continuous Production of the MEA Complex of Copper Solution

FIGURE 5

**Copper Dissolution vs Air Flow Rate
Continuous @ pH = 9.8**




FIGURE 6

**Copper Dissolution vs. Air Flow Rate
Continuous @ pH = 9.5**




FIGURE 7

Copper Dissolution Rate vs. pH
Continuous @ 6.0 SCFH Air Flow Rate

